## Suzanne Steab - April 2011 Inspection Report

From:

Karl Houskeeper

To:

Iroberts@archcoal.com; mdavis@archcoal.com

Date:

5/5/2011 8:01 AM

Subject:

April 2011 Inspection Report

CC:

Angela Nance; Daron Haddock; Suzanne Steab

Attachments: SUFCO April 2011.pdf

Mike/Leland,

Attached is the April 2011 inspection report for SUFCO.

Thanks,

Karl

Sorry the one I sent yesterday was for February.



# State of Utah

#### **DEPARTMENT OF NATURAL RESOURCES**

MICHAEL R. STYLER Executive Director

#### Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Dancacontation	es Present During the Inspection:
	Mike Davis
OGM	Karl Houskeeper

# **Inspection Report**

Permit Number:	C0410002				
Inspection Type:	PARTIAL				
Inspection Date:	Wednesday, April 06, 2011				
Start Date/Time:	4/6/2011 8:00:00 AM				
End Date/Time:	4/6/2011 3:00:00 PM				
Last Inspection:	Tuesday, March 01, 2011				

Inspector: Karl Houskeeper,

Weather: Overcast, Temp. 35 Deg. F. InspectionID Report Number: 2705

> Accepted by: jhelfric 4/12/2011

Permitee: CANYON FUEL COMPANY Operator: CANYON FUEL COMPANY

Site: SUFCO MINE

Address: 597 SOUTH SR24, SALINA UT 84654

County: SEVIER

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages	Mineral Ownership	Types of Operations	
720.48 Total Permitted	<b>✓</b> Federal	✓ Underground	
48.43 Total Disturbed	✓ State	Surface	
Phase I	County	Loadout	
Phase II	☐ Fee	Processing	
Phase III	Other	Reprocessing	

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Date

Wednesday,

Permit Number: C0410002 Inspection Type: PARTIAL

Inspection Date: Wednesday, April 06, 2011

Page 2 of 3

### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  For PARTIAL inspections check only the elements evaluated.
  Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
  Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
  Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				[]
2.	Signs and Markers	7	i.)	<b>y</b>	
3.	Topsoil	1	[]		
4.a	Hydrologic Balance: Diversions	<b>V</b>			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>y</b>		1	San San
4.c	Hydrologic Balance: Other Sediment Control Measures		phoreas		
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		F 7	[]	
6.	Disposal of Excess Spoil, Fills, Benches	5)		::1	
7.	Coal Mine Waste, Refuse Piles, Impoundments	~		~	
8.	Noncoal Waste	~			
9.	Protection of Fish, Wildlife and Related Environmental Issues		energy kan sal	)	
10.	Slides and Other Damage	Ü		E)	[]
11.	Contemporaneous Reclamation	-	\$11.10m	£11.j	
12.	Backfilling And Grading				
13.	Revegetation	[_]			
14.	Subsidence Control		ij		
15.	Cessation of Operations	-			
16.a	Roads: Construction, Maintenance, Surfacing		[]	[]	
16.b	Roads: Drainage Controls			And the	1
17.	Other Transportation Facilities			1 1	jones e Secret
18.	Support Facilities, Utility Installations	1	1.3	(111	
19.	AVS Check	1	[]	57 TE	
20.	Air Quality Permit				100
21.	Bonding and Insurance			10	
22	Other	17		:"1	:1

Inspection Continuation Sheet

Permit Number: C0410002 Inspection Type: PARTIAL

Inspection Date: Wednesday, April 06, 2011

Page 3 of 3

## 2. Signs and Markers

Mine identifications signs are located at the varied entrance points to the permit area. The signs contain the required information.

### 7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile appeared stable. No visible hazards were observed.